


Figure 1




Figure 2 shows a micrograph of a material surface. The image displays a textured, granular surface with a scale bar indicating 200 μm. The surface appears to be composed of small, irregular particles or grains, with some larger, more distinct features visible. The overall appearance is that of a rough, possibly fractured or eroded material.

Figure 2



THESE DOCUMENTS SONT LA PROPRIETE DE LA BIBLIOTHEQUE NATIONALE
ET NE PEUVENT ETRE REPRODUITS NI COMMUNIQUEES A TROISIEME PARTI
SANS LAutorISATION ECRITE DE LA BIBLIOTHEQUE NATIONALE

Figure 3






FIG. 4.

- EXTRUDED MEDIUM GRAINS
- EXTRUDED FINE GRAINS
- ▼ EXTRUDED LOW CALCIUM
- ▽ ROLLED STRIP
- CONTINUOUS CAST STRIP




FIG. 5.




FIG.6.




FIG.7.




FIG.8.




FIG.9.




FIG. 10.